

58

AIRWORTHINESS DIRECTIVE COMPLIANCE RECORD

Aircraft, Engine, Propeller, or Appliance/Comp Make CONTINENTAL Model E-225-8 Ser. No. 30254-D-4-8

| AD Number | Subject | Date and Hours at Compliance | Method of Compliance | ONE-TIME | RECURRING | Next Comp Due Date/Hours | Authorized Signature and Number |
|-----------|-------------------------|------------------------------|-----------------------------------|----------|-----------|--------------------------|---|
| | | | | X | X | | |
| 06-01 | Piston Pin Failures | 7-14-56 643 HRS. | Installed P/N 539467 Pins | X | | 9w | April 1, 1978 Angie M. Johnson II T.A. 44858696 |
| 06-04 | Generator Drive Failure | | C/w at eng. O.H. | X | | 9w | |
| 12-01 | Piston Pin Failures | 11-27-59 1654 HRS. | HAS P/N 539467 Pins installed | X | | 9w | |
| 15-01 | Exhaust Valves | 2-20-76 1938 HRS. | Install P/N 626540 Exhaust Valves | X | | 9w | |
| 18-09 | OR2 Bendix MAG | | Due at 2438.4 | | | | |

| | | | | | | | |
|-------|--------------------------|----------------------|--------------------------------|---|---|--|---|
| 26-02 | Thompson Fuel Pumps | 4-1-78 2122 HRS. | C/w for TF 1900 pump installed | X | | | April 1, 1978 Angie M. Johnson II T.A. 44858696 |
| 07-04 | Bendix Magnets' 2 | 2-20-76 1938 HRS. | C/w at Engine Overhaul | X | | | |
| 26-09 | Bendix Magnets' 2 | 4-1-78 2122 HRS. | N/A by P/N of Mag. | X | | | |
| 07-12 | Bendix Ignition Switches | 4-1-78 2122 HRS. | N/A not installed | | X | | |
| 20-01 | Bendix Mag | 11/14/91 2606.0 | N/A By S/w | X | | | |