


PROP LOG



Propeller Record General Information

Propeller Manufacturer Hartzell HC-C2YK-1B F

Model _____ Type _____


Hub Series # _____ Blade # _____

Date of Manufacture _____

Husky Make/Model
Aircraft Installed On: N71HY

Serial # 2088

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____
 Date: _____
 Next Inspection Due: _____
 Hartzell HC-C2YK-1BF Model 7666A CH 34109B TT 701.0 W/O # 2567 10/18/2017
 1. C/W a 100-hour inspection.
 2. Checked back plate, greased hub and dressed blades.

 Alfredo Olivas A&P 1988936 10/18/2017

Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____
Year: _____ Date: _____ Next Inspection Due: _____	Total Time in Service	Description
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	To in
Date: _____	
Next Inspection Due: _____	To in
Year: _____	To in
Date: _____	
Next Inspection Due: _____	To in
Year: _____	To in
Date: _____	
Next Inspection Due: _____	To in

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: _____
 Date: _____
 Next Inspection Due: _____

PROP MODEL:
 HC-C2YK-1BF
 PROP S/N:
 REG. NO. N71HY
 WORK ORDER:
 19110-11-2019

Ruby Valley Aviation L.C.

Repair Station No. Y5VR482Y
 75 Airport Road
 Twin Bridges, Montana 59754
 Phone: 406-684-5335

DATE: 12/10/2019
 A/C TSN: 893.71
 PROP TT: 893.71
 TACH: 893.71

Prop Entries

I certify that this propeller has been inspected IAW a 100hr inspection per FAR43 appendix D and has been found to be in an airworthy condition.

The items identified above were repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service for work performed. Pertinent details of this repair are on file at this repair facility under Work Order Number identified below.

DATE: 12/10/2019

SIGNED: _____

Ryan Fleming
 Certified Repair Station No. Y5VR482Y

Work Order: 19110-11-2019

Printed by EBis 3 (datcomedia.com)

Year: _____ Date: _____ Next Inspection Due: _____	Total Time in Service	Description
	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

☐ HUB & I

Year: _____

Date: _____

Next Inspection
Due: _____

Year: _____

Date: _____

Next Inspection Due: _____

Due

Yes

Date

PROP MODEL
HC-CZYK-1BF
PROP S/N
REG NO N71HY
WORK ORDER
20114-12-2020

Prop Entries

I certify this propeller was inspected in accordance with a 100hr inspection per FAR Part 43 Appendix D and was found to be in an airworthy condition.

The items identified above were repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service for work performed. Pertinent details of this repair are on file at this repair facility under Work Order Number identified below.

DATE: 1/1/2021

SIGNED: _____

Ryan Fleming
Certified Repair Station No. Y5VR482Y

Work Order: 20114-12-2020

Printed by EBis 3 (datcomedia.com)

2-1-2022 Prop Hartzell HC-CZYK-1BF S/N: CH34109B TACH: 1037.32 TSN: 1037.32

Inspected the prop for nicks, dings, cracks and leaks. Lubed with Aeroshell #6 grease.

I certify that this propeller has been inspected in accordance with a 100 hour inspection and has been determined to be in airworthy condition.

Mike Cunningham A&P 517542870

N71HY

Next Inspection
Due: _____

Time Since
Overhaul

Mech. Cert. # or Repair Station # _____

PROP MODEL
HC-C2YK-1BF
PROP S/N
REG NO N71HY
WORK ORDER
22037-01-2023

Ruby Valley Aviation L.C.

Repair Station No. Y5VR482Y
75 Airport Road
Twin Bridges, Montana 59754
Phone 406-684-5335

DATE 1/11/2023
A/C TSN 1045 32
PROP TT 1045 32
TACH 1045 32


Prop Entries

I certify this propeller was inspected in accordance with a 100hr inspection per FAR Part 43 Appendix D and was found to be in an airworthy condition.
Dressed blades

The items identified above were repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service for work performed. Pertinent details of this repair are on file at this repair facility under Work Order Number identified below

DATE: 1/11/2023

SIGNED:



Work Order: 22037-01-2023

Michael Haisten
Certified Repair Station No. Y5VR482Y

Printed by EBis 3 (datcomedia.com)

Mech. Cert. # of repair station #

Year Date Next Inspection Due	Total Time In Service	Description
	Time Since Overhaul	Mech. Cert. # or Repair Station #

☐ HUB & SPIN

Year: _____
Date: _____
Next Ins Due: _____

PROP MODEL
HC-C2YK-1BF
PROP S/N
REG NO N71HY
WORK ORDER
24003-01-2024

Ruby Valley Aviation L.C.

Repair Station No Y5VR482Y
75 Airport Road
Twin Bridges, Montana 59754
Phone 406-684-5335

DATE 1/18/2024
A/C TSN 1061 84
PROP TT 1061 84
TACH 1061 84


Prop Entries

I certify that this propeller has been inspected IAW a 100 hour inspection within the scope and detail of FAR 43 appendix D using and found to be in an airworthy condition

The items identified above were repaired and inspected in accordance with current maintenance rules of the Federal Aviation Regulations and is approved for return to service for work performed. Pertinent details of this repair are on file at this repair facility under Work Order Number identified below

DATE 1/18/2024

SIGNED




Work Order: 24003-01-2024

Printed by EBis 3 (datcomedia.com)

Michael Haisten
Certified Repair Station No Y5VR482Y

Mech. Cert. # or Repair Station # _____

Year:	Total Time in Service	Description
2025	1112.79	ANNUAL INSPECTION COMPLETED WITH IN ACCORDANCE WITH FAR 43 APPENDIX D AND DETERMINED IN CONDITION FOR SERVICE
Date:	Time Since Overhaul	Mech. Cert. # or Repair Station #
1 JAN		 AWP 3524309 IA
Next Inspection Due:		


Date: ~~01/20/2026~~ ²⁻¹⁻²⁶ **Hours:** TAF: 1125.88 Tach: 1125.86 TTE: 1125.88 TTP: 1125.88
Tail#: N71HY
Make: Aviat **Model:** A-1B **S/N:** 2088

Hartzell HC-C2YK-1BF S/N CH34109B

I certify that this propeller has been inspected IAW a 100 hour inspection within the scope and detail of FAR 43 appendix D and found to be in an airworthy condition. Dressed nicks in blades.

Name: Michael Haisten
Co: Ruby Valley Aviation

Cert: AP3054755IA

Sign: 

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____