HARTZELL

# PROPELLER OWNER'S MANUAL



HARTZELL

# PROPELLER LOGBOOK

PROPELLER MODEL BHC-J2YF-1BF

PROPELLER S/N EF2910B

Logbook #1
N131EG

## PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model BHC-J2YF-1BF

Propeller S/N EF290B

Blade Design F7694

Blade S/N's

No. 1 J77522

No. 2 J77526

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/~~Feather~~ 35.0°

Start Lock N/A

Low 14.6°

Reverse N/A

Aircraft Manufacturer CIRRUS

Aircraft Model SR20

S/N 1248

Registration N308PG

| Date | Propeller TSN | Propeller TSO | A/C Hrs | Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections. |
|---|---|---|---|---|
| | | | | |
| | | | | **Southeast Aero Services, Inc. - St. Augustine, FL**<br>**Cirrus SR20 s/n 1248 N904CD**<br>**8, October 2003** **Total Time: ~~466.2~~** 93.2 ftsn<br>**Propeller: Hartzell PHC-J3YF-1MF**<br>1. Completed an Annual Inspection in accordance with Cirrus Maintenance Manual Chapters 5-10 & 5-20.<br>2. Lubricated propeller hub per Hartzell maintenance instructions.<br>3. Dressed blades as required.<br>4. No propeller AD's due at this time. See AD compliance list for additional details.<br>***I certify this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time.***<br>***James T. Markey A&P154623664IA*** James T Markey |
| | | | | **Southeast Aero Services, Inc. - St. Augustine, FL**<br>**Cirrus SR20 s/n 1248 N904CD**<br>***September 2004*** ***Total Time: 258.6***<br>***Hartzell PHC-J3YF-1MF***<br>1. Completed an Annual Inspection in accordance with Cirrus Maintenance Manual Chapters 5-10 & 5-20.<br>2. Lubricated propeller hub per Hartzell maintenance instructions.<br>3. Dressed blades as required.<br>4. No propeller AD's due at this time. See AD compliance list for additional details..<br>***I certify this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time.***<br>***James T. Markey A&P1546236641A*** James T Markey |
| | | | | |

Cirrus SR-20 s/n 1248 N308PG

22 November 2006 Tach Time: 685.0

Propeller: Hartzell PHC-J3YF-1MF

1. Complete an Annual Inspection in accordance with Cirrus Maintenance Manual Chapters 5-10 & 5-20.
2. Lubricated propeller hub per Hartzell maintenance instructions.
3. Dressed blades as required.
4. No propeller AD's due at this time.

I certify this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time.

Steven Paone A&P364662332IA

| Date | Propeller TSN TSO | A/C Hrs | Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections. |
|---|---|---|---|

Cirrus SR-20 s/n 1248 N308PG

14 November 2007 Tach Time: 842.5

Propeller: Hartzell PHC-J3YF-1MF

1. Complete an Annual Inspection in accordance with Cirrus Maintenance Manual Chapters 5-10 & 5-20.
2. Lubricated propeller hub per Hartzell maintenance instructions.
3. Dressed blades as required.
4. No propeller AD's due at this time. Steven Paone

I certify this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time.
Steven Paone A&P364662332IA

Date: 11/10/2008; Aircraft: N308PG; Type: SR20; S/N: 1248; Hobbs: 943.7; Total Time: 943.7; Engine - Type: IO-360ES6, S/N: 357487, Time: 943.7; Prop - Type: PHC-J2YF-1BF, S/N: EF290B, Time: 943.7
***Prop Work*** ID 4296

Completed an Annual inspection in accordance with the Cirrus Design SR20 Inspection Form and Service Manual. AD 08-13-28 (7/17/08) propeller hub lube hole inspection, not applicable by prop model number, prop not left hand rotating. Ground run for ops and leak ck good.

I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.

Benjamin J. Pitterle
A&P390747277 IA

Benjamin J. Pitterle IA 390747277

☐ Wisconsin Aviation - Madison
3606 Corben Court
Madison, WI 53704
608-268-5003

☒ Wisconsin Aviation - Watertown
1741 River Drive
Watertown, WI 53094
920-261-4567

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 11-6-09**

| A/C N# | MAKE | MODEL | A/C S/N | HM | TSPOH |
|---|---|---|---|---|---|
| 308PG | Cirrus | SR20 | 1248 | 1000.3 | 1000.3 |

Inspected prop I.A.W. an annual inspection and found airworthy. Greased prop hub. Dressed and painted prop blades.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: _____ Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation., 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 12-1-10**

| A/C N# | MAKE | MODEL | A/C S/N | HM | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1218 | 1043.2 | 1043.2 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: _____ Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation., 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858

| Date | Propeller TSN | Propeller TSO | A/C Hrs | Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections. |
|---|---|---|---|---|

**FINEFIELD AVIATION**

**PROPELLER LOG** — **DATE: 1-5-12**

| A/C N# | MAKE | MODEL | A/C S/N | HM | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1083.6 | 1083.6 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: _____ Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation, 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858

**FINEFIELD AVIATION**

**PROPELLER LOG** — **DATE: 2-9-13**

| A/C N# | MAKE | MODEL | A/C S/N | HM | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1130.6 | 1130.6 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades. Dressed prop hub. Painted prop blade faces flat black

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: _____ Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation, 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 3-14-14**

| A/C N# | MAKE | MODEL | A/C S/N | HM | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1218 | 1160.8 | 1160.8 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades. Greased prop hub.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation., 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 4-2-15**

| A/C N# | MAKE | MODEL | A/C S/N | HM | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1209.3 | 1209.3 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades. Greased prop hub.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation., 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858

| Date | T |
|---|---|

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 5-6-16**

| A/C N# | MAKE | MODEL | A/C S/N | TACH | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1244.7 | 1244.7 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation. 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 6-21-17**

| A/C N# | MAKE | MODEL | A/C S/N | TACH | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1291.1 | 1291.1 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades. Greased prop hub.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation. 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 7-5-18**

| A/C N# | MAKE | MODEL | A/C S/N | TACH | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1316.9 | 1316.9 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades. Greased prop hub.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation., 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858

## FINEFIELD AVIATION

**PROPELLER LOG** — **DATE: 8-7-19**

| A/C N# | MAKE | MODEL | A/C S/N | TACH | TSPOH |
|---|---|---|---|---|---|
| 131EG | Cirrus | SR20 | 1248 | 1336.9 | 1336.9 |

Inspected prop I.A.W. an annual inspection and found airworthy. Dressed prop blades.

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA
For Finefield Aviation., 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858

IA 3534832 86

| Date | Propeller TSN TSO | A/C Hrs | Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections. |
|---|---|---|---|

**Finefield Aviation** **Propeller Log** **Serv Date: 9/5/20** 4267

| Aircraft | Type | S/N: | Tach: | TSPOH: | TTAF: | Hobbs |
|---|---|---|---|---|---|---|
| 131EG | Cirrus-SR20 | 1248 | 0 | 1365 | 1365 | 1365 |

I certify this Propeller has been inspected I.A.W. with an ANNUAL INSPECTION, and was determined to be in airworthy condtion. I.A.W. the Cirrus maintenance manual.Dressed propeller blade leading edges. |

This aircraft has been found airworthy for return to service with respect to the work described herein.

Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA

For Finefield Aviation, 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858 4267

**Finefield Aviation** **Propeller Log** **Serv Date: 11/23/21** 4640

| Aircraft | Type | S/N: | Tach: | TSPOH: | TTAF: | Hobbs |
|---|---|---|---|---|---|---|
| 131EG | Cirrus-SR20 | 1248 | 0 | 1392 | 1392 | 1392 |

I certify this Propeller has been inspected I.A.W. with an ANNUAL INSPECTION, and was determined to be in airworthy condtion, I.A.W. the Cirrus maintenance manual.Dressed propeller blade leading edges. |

This aircraft has been found airworthy for return to service with respect to the work described herein.

Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA

For Finefield Aviation, 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858 4640

## Finefield Aviation — Propeller Log

Serv Date: 2/2/23 — 4946

| Aircraft | Type | S/N: | Tach: | TSPOH: | TTAF: | Hobbs |
|---|---|---|---|---|---|---|
| 131EG | Cirrus-SR20 | 1248 | 0 | 1413.3 | 1413.3 | 1413.3 |

I certify this Propeller has been inspected I.A.W. with an ANNUAL INSPECTION, and was determined to be in airworthy condtion. I.A.W. the Cirrus maintenance manual.Dressed prop blade leading edges.

This aircraft has been found airworthy for return to service with respect to the work described herein.

Authorized Signature: Jim Finefield Printed Name: James Finefield AP 353483286 IA

For Finefield Aviation, 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858 — 4946

## Finefield Aviation — Propeller Log

Serv Date: 3/21/24 — 5278

| Aircraft | Type | S/N: | Tach: | TSPOH: | TTAF: | Hobbs |
|---|---|---|---|---|---|---|
| 131EG | Cirrus-SR20 | 1248 | 0 | 1424.2 | 1424.2 | 1424.2 |

I certify this Propeller has been inspected I.A.W. with an ANNUAL INSPECTION, and was determined to be in airworthy condtion. I.A.W. the Cirrus maintenance manual.Dressed propeller blade leading edges.

This aircraft has been found airworthy for return to service with respect to the work described herein.

Authorized Signature: Justin Finefield Printed Name: Justin Finefield AP: 3107379IA

For Finefield Aviation, 8399 Pyott Road, , Lake in the Hills, IL 60156 Phone: 815-459-4858 — 5278

| Date | Propeller TSN TSO | A/C Hrs | Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections. |
|---|---|---|---|

## Finefield Aviation — Propeller Log

Serv Date: 5/6/25 — 5579

| Aircraft | Type | S/N: | Tach: | TSPOH: | TTAF: | Hobbs |
|---|---|---|---|---|---|---|
| 131EG | Cirrus-SR20 | 1248 | 1429.3 | 1429.3 | 1429.3 | 0 |

I certify this Propeller has been inspected I.A.W. with an ANNUAL INSPECTION, and was determined to be in airworthy condtion, I.A.W. the Cirrus maintenance manual.Dressed propeller blade leading edges. | Lubed propeller hub with Aeroshell #6 grease. |

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: Jim Finefield Printed Name:James Finefield AP 353483286 IA
For Finefield Aviation, 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858 — 5579

## Finefield Aviation — Propeller Log

Serv Date: 7/20/26 — 5911

| Aircraft | Type | S/N: | Tach: | TSPOH: | TTAF: | Hobbs |
|---|---|---|---|---|---|---|
| 131EG | Cirrus-SR20 | 1248 | 0 | 1438 | 1438 | 1438 |

I certify this Propeller has been inspected I.A.W. with an ANNUAL INSPECTION, and was determined to be in airworthy condtion, I.A.W. the Cirrus maintenance manual.Dressed propeller blade leading edges. | Lubed propeller hub with Aeroshell #6 grease. | All airworthiness directives (ADs) are current through the latest FAA AD Bi-Weekly 2026-14. |

This aircraft has been found airworthy for return to service with respect to the work described herein.
Authorized Signature: James Finefield Printed Name:James Finefield AP 353483286 IA
For Finefield Aviation, 8399 Pyott Road, Lake in the Hills, IL 60156 Phone: 815-459-4858 — 5911