

Kim Davidson Aviation Inc.

2701 Airport Ave.
Santa Monica, CA. 90405
Phone (310) 391-6293
Fax (310) 391-6294



FAA Repair Station # YYKR678L

N21LZ

SR22 s/n 0267 yr 7/2002

Engine Total Time: 1804.7
Engine TSMOH: 152.7
(OH Exchange Eng Installed 9/2019)

Aircraft Total Time: 2033.9

Prop Total Time: 2033.9
Prop TSPOH: 152.7

Status Sheet

<u>Item</u>	<u>C/W</u> <u>Date</u>	<u>C/W</u> <u>Hobbs</u>	<u>Time</u> <u>Interval</u>	<u>Date</u> <u>Due</u>	<u>Due @</u> <u>Hobbs</u>
1. ANNUAL Inspection	6/2025	2033.9	12 Mo.	6/2026	-----
2. FAR 91.411 & 91.413	6/2025	2033.9	24 Mo.	6/2027	-----
3. FAR 91.207 ELT Inspection	6/2025	2033.9	12 Mo.	6/2026	-----
4. ELT Battery Replacement	11/2018	1834.0	See Battery	3/2027	-----
5. ELT Remote Switch Battery	9/2019	1881.2	7 Yrs.	9/2026	-----
6. CAPS Rocket Replacement	3/2024	2022.4	10 Yrs.	11/2033	-----
7. CAPS Parachute Repack	3/2024	2022.4	10 Yrs.	10/2033	-----
8. CAPS Line Cutters Replace	12/2021	1977.1	6 Yrs.	5/2027	-----
9. LH/RH Magneto 500Hr Insp.			500 Hrs.	-----	2381.2
10. LH/RH Magneto Overhaul			4 Yrs.	9/2023	-----
11. Fuel Injector Nozzle Service	6/2025	2033.9	1 Yr./300 Hrs.	6/2026	2333.9
12. #1 Main Battery Replace	6/2025	2033.9	On Condition	-----	-----
13. #2 Batteries Replacement	6/2025	2033.9	2 Yr./500 Hrs.	6/2027	2533.9
14. Propeller Overhaul	9/2019	1881.2	6 Yrs./2400 Hrs.	9/2025	4391.2
15. Prop Governor Overhaul	9/2019	1881.2	5 Yrs./2000 Hrs.	9/2024	3881.2
16. #1 Alternator 500hr Inspect	9/2019	1881.2	500 Hrs.	-----	2381.2
17. #2 Alternator Overhaul	9/2019	1881.2	1700 Hrs.	-----	3581
18. Sandel HSI Bulb Replace	9/2015	1621	1 Yr./1000 Hrs.	9/2016	2621
19. OAT/Clock Battery Replace	6/2025	2033.9	12 Mo.	6/2026	-----
20. Aileron/Rudder Bungee	6/2025	2033.9	5 Yrs.	6/2030	-----
21. Brake Caliper O-rings Repl.	6/2025 L	6/2025 R	5 Yrs./On Cond.	6/2030 LH	6/2030 RH
22. Electric Fuel Pump Replace			10 Yrs.	7/2012	
23. Flexible Fuel Lines Replace	9/2019	1881.2	On Condition	Teflon Hoses	Installed
24. Exhaust Heat Exchanger	5/2018	1804.2	1000 Hr.	OH Exhaust	2804.2
25. Fire Extinguisher Replace	6/2025	2033.9	12 Yrs./On Cond	6/2037	-----
26. AD 93-05-06 Ignition Switch	9/2019	1881.2	2000 Hrs.	-----	3881.2