


30 November 2023

To whom it may concern:

Clutch assembly P/N: C018-2, comprising P/N: C166-4 shaft S/N: 6910, and Sprag assembly P/N: C188-3 S/N: 398, was removed serviceable from Robinson R44 Raven I S/N: 0695 Registration ZK-HKP on 29 November 2023 at 3481.7 airframe hours, as due a 12 yearly inspection IAW Robinson R44 Maintenance Manual Section 1.102 - Additional Component Maintenance.

The assembly has done 1285.7 hours TSN, 495.3 TSI (R44 MM Chapter 1, Table 1), and was due a 12-year inspection on 5 April 2023.

Sincerely,



Greg Newton  
Hangar Manager  
Argus Aviation NZAP