

## **1949 Ryan Navion N4815K**

1. Annual 08/2023: Annuals completed by Navion Owner IA
2. Logs since new
3. NO damage history
4. Total Time Airframe: 4400.9
5. Continental IO-520BB TTSOH: 746.5, 1749.5 SNEW
6. McCauley 3-blade: TTSNEW 746.5
7. Left Wing fuel tank access panel-installed 1957
8. Beef-up Kit installed-1997
9. Interior installed-2002 : 8/10
10. Painted-2002 & touched up 2018: 8/10
11. New ANS Fuel Valve-2017
12. Nose Strut & Main gear new seals and hardware-2017
13. Flexible fuel hoses replaced-2017
14. Fuel Transfer system installed-2017
15. Master Hydraulic Power & Control valve rebuilt by Ron Judy-2018
16. All flight cables, pulleys and hardware replaced with new-2018
17. Hooker shoulder harnesses
18. Palo Alto Tail & Texas Patch
19. Gear warning light synched to gear unsafe horn.
20. Pilot side Cleveland toe brakes
21. Oil analysis since 2016
22. Engine oil heater
23. Whelen wing tip strobes
24. Leading edge wing vents
25. Bruce's canopy cover

### **AVIONICS/ADDED Accessories**

- Garmin GTN-650 GPS/NAV installed-2016
- Apollo SL30 w/ILS
- Garmin G5 (2018) & Garmin G5 DG/HSI (2020)
- STEC 55X Autopilot (2020)
- Bendix/King KT-74 ADS-B out (2017)
- Garmin GDL39 ADS-B in & weather
- PS Engineering PMA6000M-C audio panel w/4 place intercom
- Insight Graphic Engine Monitor FS-450 EGT/CHT
- JPI Fuel Scan 450 Fuel Flow monitor
- Navion maintenance, parts and repair manuals

### **Extra Parts w/full price purchase**

- Extra master hydraulic power & control valve- rebuilt by Ron Judy 2018
- Wing Jacks

4reed@ezlink.com: c) 970-420-7055: Russell Reed