



SUNRISE HELICOPTER, INC.

International Engine Sales and Support



C20 ACCESSORIES

FUEL CONTROL: PN 2524644-31 TO -32 AT \$7190 EXCHANGE. The only items that could be potentially billed back would be a failed Inconel bellows assembly, start derichment bellows, broken or missing parts, and both throttle shaft and throttle cam profile wear found during tear down inspection. Outright price \$17,750.00

GOVERNOR PN 2524667-14 THRU -16 AND 2524769-13 THRU -15 \$5075 EXCHANGE AND 2549170-1 THRU -3 AT \$5495 EXCHANGE. Outright price \$7,200.00 for PN 2524667-16. Outright price for PN 2549170-3 is \$8,200.00

FUEL PUMP PN 6899253 AT \$1850 EXCHANGE. Outright price \$5,200.00

BLEED VALVE PN 23053176 \$825 EXCHANGE. Outright price \$1,350.00

FUEL NOZZLE PN 23077068 AT \$1725 EXCHANGE. PN M250-10603 AT \$1025 EXCHANGE. Outright price \$2,200.00

Note: All cores must be in as removed condition and suitable for overhaul

C28 ACCESSORIES

FUEL CONTROL PN 2524738-38 EXCHANGE AT \$7385. The only items that could be potentially billed back for would be a failed Inconel bellows assembly, start derichment bellows, broken or missing parts and both throttle shaft and throttle cam profile wear found during tear down inspection. Outright price \$17,750.00

GOVERNOR PN 2524677-11 thru -13 AT \$5075 EXCHANGE. Missing or broken part are a bill back. Outright price \$6,800.00

FUEL PUMP PN 6896822 AT \$2190 EXCHANGE. Outright price \$6800

BLEED VALVE PN 23005455, 23005367 AND 23074227 AT \$2290 EXCHANGE. Outright price \$4,200.00

FUEL NOZZLE PN 23077067 AND 23077188 AT \$1725 EXCHANGE AND PN M250-10604 AND M250-10606 AT \$1025 EXCHANGE. Outright price \$2,200.00

Note: all cores must be in "as removed" condition and suitable for overhaul

C30 ACCESSORIES

FUEL CONTROL PN 2549092-7THRU -9 AT \$7,475 EXCHANGE. The only items that could potentially be billed back for would be a failed Inconel bellows assembly, start derichment bellows, broken or missing parts and both throttle shaft and throttle cam profile wear found during tear down inspection. Outright price \$17,750.00

GOVERNOR PN 2524692-12 AT \$5100 EXCHANGE AND PN 2549172-1 THRU -3 AT \$6100 EXCHANGE. Missing or broken parts are a bill back.

Outright price for PN 2524692-12 is \$8,275.00; Outright price for 2549172-3 is \$9,500.00

FUEL PUMP PN 6896822 AT \$2190 EXCHANGE. Outright price \$7,800.00

BLEED VALVE PN 23005456, 23005366 AND 23073353 AT \$2290. EXCHANGE. Includes replacement of poppet and servo valves. Outright price \$3,800.00

FUEL NOZZLE PN 23077067 AND 23077188 AT \$1725 EXCHANGE AND PN M250-10604 AND M250-10606 AT \$1025 EXCHANGE. Outright price \$2,200.00

Note: all cores must be in as removed condition and suitable for overhaul

STARTER GENERATORS

PN 23032-027 OH 8130 HELI-TECH \$2,650.00 Outright

PN 200SG124Q OH 8130 HELI-TECH \$4,200.00 Outright

PN 150SG111Q OH 8130 HELI-TECH \$4,400.00 Outright

\\SERVER6\G-SERVER5\SUNRISE 250 MAIL OUTS\RR ACCESSORIES- STARTERGEN PRICING 2021.DOCX