

N5634Q 1990 Beech B58 Baron

Location:

FYV

AFTT:

5654

Serial Number:

TH-1598

Engine:

Engines: Continental IO-550-C

Left Engine SN: 824290

Left Engine SMOH: 1330.2-254 Hrs on new cylinders (1900TBO)

Right Engine SN: 824289

Right Engine SMOH: 1330.2-254 Hrs on new cylinders (1900TBO)

Prop:

Left Prop SN: 941457 Left Prop SPOH: 1330.2 Right Prop SN: 900834 Right Prop SPOH: 1330.2

Avionics:

PS Eng. 8000B Audio Panel GNS-530W KX 155 330ES

Avionics Continued:

KT 76A
GI 275 AHARS
King HSI
KFC 200 with Flight Director
Bendix WX Radar

Additional Equipment:

Cabin Heater
Auxiliary Fuel Tank
3-Bladed Aluminum Heated Props
Wing & Tail De-Ice Boots, Windshield Hot Plate
Sheepskin-Covered Crew Seats
Window Inserts
Executive Writing Table
Factory Air Conditioning
ADS-B Capable
WAAS
Rosen Sunvisor

Rosen Sunvisor Heated Windshield Engine Monitor Dual Aft Baggage Doors

Condition:

Exterior: Overall White with Black Stripes & Gold Accents.Great Condition 2004

Interior: Passenger Seating in an Executive Club Configuration, Light Gray Leather Sidewalls and Headliner, Light Oak Wood Accents, Left Side

Executive Writing Table

Windshield/Windows: Good

Inspection Status/Maintenance:

Annual Inspection: January 2023

Pitot Static, Altimeter, and Transponder checks: April 2023

Useful Load: 1505 lbs

Damage History: None Known Complete Logs: Yes