



AIRCRAFT DELIVERY RECORD

Document-No:
FPO-0010-005

Issue: A00
Replaces issue: -

Page 1 of 1

Registration: N209ZM

Aircraft Type:	PIPISTREL	Power plant	Propeller
Type:	ALPHA Trainer	Rotax 912 UL2-01	Helix FP02-80
S/N:	930 AT 912 LSA	9580487	180524
Date of production:	September 2018	2018	2018

Equipment	Qty	W	Equipment	Qty	W
VSI: KANARDIA vario, sn: 07754	1		GARMIN GAD29, sn: 366002172	1	
ASI: KANARDIA asi, sn: 09140	1		Monitor: KANARDIA DIGI, sn: 07433	1	
ALTI: KANARDIA vsi, sn: 08160	1		Antenna: CI 157P, sn: 569708	1	
Libela: WINTER	1		Pitot tube: GARMIN GAP 26, sn: 34F001134	1	
12V Socket: HELLA	1		ELT: Artex 345, sn: 267-13560	1	
COM: GARMIN GNC255, sn: 2A8019806	1		GRS Rescue System, SN: 7570-18-4806-8666	1	
XPDR: GARMIN GTX335, sn: 3EE421041	1		Electric Elevator Trim	1	
Magnetic Compass: CM24, sn: CM24170710	1		Equipment, Manual, Records	Qty	W
RPM: KANARDIA RPM, sn: 08212	1		Main Landing Gear Tyres	2	
Eng. Box: KANARDIA DAQU, sn: 09410	1		Nose Wheel Tyre	1	
Antenna: GARMIN GA35, sn: 149110	1		Seat Belts	YES	
Antenna: GARMIN GA56, sn: 59441347	1		Solid Luggage container	YES	
GARMIN GI260, sn: 3GQ001623	1		Aircraft First-Repair-Aid and Toolkit:	YES	
GARMIN GMA245, sn: 3YL002151	1		Pitot Tube Cover	YES	
GARMIN GTN650, sn: 1Z8025727	1		Beringer Brake System + Parking brake	YES	
GARMIN GSU25, sn: 2SA003287	1		Aircraft Manuals	YES	
GARMIN G5, sn: 4JQ019142	1		LSA Documentation Pack	YES	
GARMIN G5, sn: 4JQ019153	1				
GARMIN G5, sn: 4JQ019373	1				

Date: 26. September 2018

Prepared by:

Manufacturer



Signature: Andraž Brecej

Signature: Peter Boscarol