



1967 V35A-TTAF 5185, Cont. IO520 TSMOH 1789 crack in top of engine case, mechanic damaged wing, needs repair. Hartzell prop. Beautiful plane, should be flying! GNS 530 Nav, GTX 330 Mode S XPNDR, ECI Engine analyzer, Gami injectors, auto pilot, Osborne tip tanks, six seats, Rosen visors, Whelen lndg light, D'Shannon windshield, Tanis preheat, air skeg, dual yoke. \$55,000, needs on site repair prior to flight or ground transport. Ann 09/22 MI 269-998-9332 or nancyccim@icloud.com

