

AIRFRAME MAINTENANCE RECORDS

			Log No.
		10. N2525Y	
Aircraft Mfg. Piper	Model_P	A28-161.	Serial No. <u>78</u> - 851 6075
Engine Mfg. Lycoming	Model <u></u>)320-D3G	Serial No. RL ~ 17639-39 A
Engine Mfg.	Model		Serial No.
Propeller Mfg. Sensenich Hub Design No.			Serial No. A - 5726S
Blade Design No		Blade Serial No	p's
Propeller Mfg.	_ Model		Serial No
Blade Design No.		Blade Serial No	's
(All applicable	Information must be filled	



AEROTECH PUBLICATIONS INC

www.adlog.com P.O. Box 1359 / Southold, NY 11971-0965

TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	N2525Y TACH: 6096.2 DATE: 20 AUG. 2014 REPLACED LEFT MAIN TIRE PIN 6.00-6 6PLY. 8 TUBE PIN 6.00-6, AND REPACKED WHEEL BEARINGS.	WORK			DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	N2525Y TACH: 6135.9 DATE: 23 OCT. 2014 REPACKED (RIGHT/PILOT) MASTER CYLINDER (3) O-RINGS: (2) PIN MS28775-110, AND PIN MS28775-113.	Page No
	TOTAL			100	100		C.	TOTAL b	r¢	
	-	TRA .							201	
		Dand Ap 3685842							Litue A= P3689862	
		ALL MARKET STATE OF THE STATE O			1					
		Control of the contro						-		
		N2525Y TACH: 6103.1 DATE: 12 SEP. 2014			1		-		N2525Y TACH: 6155.9 DATE: 18 NOV. 2014	
		REPLACED LEFT NAV LIGHT P/N T7512-12.		1	4				REPACKED NOSE STRUT PIN TPNS-1.	
		7-06/57017080 [1		-	1	-1-			V.10	
		- 10 G-01/0801A		-					Blo 12 19 862	
				- 10						
				- 1					68 .0.24	
		Andrew		100	1					
	-	N2525Y TACH: 6115.3 DATE: 22 SEP. 2014							N2525V TARIL 0450 4 PART OF	
		REPLACED (TOP) COWLING RIGHT (2) CLASP PINS PIN MS20392-1C21.		1					N2525Y TACH: 6158.4 DATE: 2 DEC. 2014	
		201	}	-		No.	ERHALIL SE	TRUMENT OV	REMOVED ALTERNATOR, AND REINSTALLED AFTER REPAIR. REPLACED MASTER SWITCH P/N 688-169.	
		Dan 1 3689 860)				MEGOLING laishell Ave	OF SAN E		
	0			1,150			CA 92020	El Cajon.	4 03/00/	
				-			च्येत्रमः) शहरत्व	AA Repair S	15 had ARP3689865	
				- 5085						,
		N2525Y TACH: 6119.9 DATE: 24 SEP. 2014							N2525Y TACH: 6170.1 TTAF: 17,624.2 DATE: 8 DEC. 2014	
		REPLACED RIGHT (2) BRAKE LININGS P/N RA66-109 REPACKED RIGHT BRAKE CALIPER O-RING P/N MS28775-222.		1335					LURED & INSPECTED FUCHT CONTROL LUNGS PRINTERS & BOWL.	
		THE NOTED HOLD BRAKE CALIFER O-KING PIN MS28775-222.		- 133					ELEVATOR TRIM JACKSCREW ASSY. REPLACED INDUCTION FILTER BA-16, AND VACUUM FILTER PIN RA-B3-51.	
		A 1	,						I CERTIFY THAT THIS <u>AIRCRAFT</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	1
		Allen #2 03689862							TOUTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.	
				100					Jane 1483689862	
	Į.				f +					!
		N2525Y TACH: 6131.5 DATE: 13 OCT. 2014			-				N2525Y TACH: 6175.2 DATE: 11 DEC, 2014	
		REPLACED IGNITION SWITCH PIN 10-357200-1.								
		1		200					REPLACED VOLTAGE REGULATOR PAN B-06331-2 (SAN 27732), BATTERY SOLENOID DIODE PAN 456-728, AND COOLING ASSEMBLY RECTIFIER PAN RS110415XXZU.	.,
		021								
	, , , , , , , , , , , , , , , , , , ,	ACM 3689860							ALL ALPSESSES	
	SUB-TOT			105				SUB-TOT		
- 1	TOTAL-C					-	——	-32 1011		

27 1200 200

age No			N2525Y TACH: 6175.2 DATE: 12 DEC. 2014		į.					
DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	REPAIRED TOP COWLING (INSTALLED PATCH ON RIGHT SIDE ABOVE REAR LATCH) WORK ACP3(84862	0	die	DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	N2525Y TACH: 6270.0 TTAF: 17,724.1 DATE: 4 APR. 2015 CHARGED BATTERY, CLEANED FUEL STRAINER SCREEN & BOWL. LUBED & INSPECTED FLIGHT CONTROL HINGES, PULLYS, FLAR MECH. & ELEVATOR TRIM JACKSCREW ASSY. REPLACED INDUCTION FILTER BA-16, AND VACUUM FILTER PM RA-83-5-1. REPLACED RIGHT MAIN TIRE PM 6.00-6 GPLY., AND REPLACED WHELL BEARINGS. I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. ACCUSED.	yPage No
			N2525Y TACH: 6183.9 DATE: 13 JAN. 2015 REPLACED LANDING LIGHT SWITCH PIN 587-827. ACP 3665862						N2525Y TACH: 6278.0 DATE: 9 APR. 2015 REPLACED NAV LIGHT POTENTIOMETER SWITCH PIN 587-779. A-236 8-54-40	
2/12/15		0	PITOT KEK ISOSTELL TO BOD INTE FORM DITOT TUBE TO WINS TUBE ENSTRUMENT OVERHAUL SERVICE OF SAN DIEGO, INC. 1881 N. Marshall Ave B Cagon, CA 92020 FAA Plepair Station CBSR417L FAA Plepair Station CBSR417L REMOVED TACHOMETER, AND REINSTALLED AFTER REPAIR. REMOVED TACHOMETER, AND REINSTALLED AFTER REPAIR.						N2525Y TACH: 6309.2 DATE: 13 MAY 2015 REPLACED STALL WARNING HORN ASSEMBLY PIN 35214-00 (WITH A SERVICEABLE UNIT). N2525Y TACH: 6331.3 DATE: 30 JUNE 2015 REPLACED (CO-PILOT) PUSH-TO-TALK SWITCH PIN S2870-1.	
		SUB-TOT	N2525Y TACH: 6231.8 DATE: 18 MAR. 2015 REMOVED TACHOMETER, AND REINSTALLED AFTER REPAIR. ACP 3682860	-01	30				N2525Y TACH: 6370.5 TTAF: 17,824.6 DATE: 13 AUG. 2015 CHARGED BATTERY, CLEANED FUEL STRAINER SCREEN & BOWL. LUBED & INSPECTED FLIGHT CONTROL HINGES, PULLYS, FLAP MECH. & ELEVATOR TRIM JACKSCREW ASSY. REPLACED INDUCTION FUTER BA-16, VACUUM FILTER PAN RA-B3-5-1, AND INSTRUMNET FILTER PIN RA-D8-18-1. CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN INHUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. **TOTAL PROPERTY OF THE PROPERTY OF THE PARTY OF TH	

7- 1

No			N2525Y TACH: 6471.3 TTAF: 17,925.4 DATE: 25 SEP. 2015							NOCOPY TABLE CARE TO BATTLE AS A TO THE TABLE
TE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	CHARGED BATTERY, CLEANED PUEL STRAINER SCREEN & BOWL. LUBED & INSPECTED FLIGHT CONTROL HINGES, PULLYS, FLAP MECH. & ELEVATOR TRIM JACKSCREW ASSY. REPLACED INDUCTION FILTER BA-16, VACUUM FILTER PIN RA-83-5-1, ALL (4) BRAKE I NININGS PIN RAGGE-100) WORK			DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	N2525Y TACH: 6496.5, DATE: 19 OCT. 2015 Page No. REPLACED LANDING LIGHT PIN GE-4595.
		TOTAL bro	AND MIXTURE CONTROL CABLE BOLT P/N 400-055, REPACKED BOTH BRAKE CALIPERS (2) O-RINGS P/N MS28775-222	4		1	7 PAG N		TOTAL br	ACP3658862
			1 CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A 30 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.				Service School		IOIAL	Blue
_			11 Blue Net 3689813							
-			Attio del				W.			
4				/						
			N2525Y TACH: 6471.3 DATE: 25 SEP. 2015							N2525Y TACH: 6518.6 DATE: 3 NOV. 2015
			REPAIRED TOP COWLING (INSTALLED PATCH BEHIND		1	ŀ				REPLACED LEFT WING REAR NAV LIGHT PIN 34-0412070-63,
7			LEFT/REAR LATCH, RIGHT/FRONT ETCH, AND RIGHT/REAR LATCH); REPAIRED BOTTOM COWLING (INSTALLED 2 PATCHES ON:		-					AND THROTTLE CONTROL CABLE P/N MC455-350.
1			BOTTOM COWLING RIGHT VENT).			i i				114
4			15 the AEP3684860			1				4 1 2 2
						1				A \$ 7 8824313
		1	(10)							
\pm			N2525Y TACH: 6471.3 DATE: 25 SEP. 2015							N2525Y TACH: 6519.3 DATE: 19 NOV. 2015
-			REPLACED NOSE TIRE P/N 5.00-5 6PLY.,			Ì				RÉPLACED (PILOT) PUSH-TO-TALK SWITCH PIN S2870-1.
			AND REPACKED WHEEL BEARINGS. REPLACED LEFT MAIN TIRE P/N 6.00-6 6PLY.,							
			AND REPACKED WHEEL BEARINGS. REPACKED NOSE STRUT PIN TPNS-1.							
			(121)							AEP3689802
7		-	12 pt A 803688812	-	-					
-		— i	9, 1							
-										Minghe meaning summary and summary plantament of the plantament interest manufactures and appropriate
			N2525Y TACH: 6477.6 DATE: 30 SEP. 2015	1						N2525Y TACH: 6529.1 DATE: 14 DEC. 2015
			REPLACED RIGHT NAV LIGHT P/N T7512-12.							REPACKED NOSE STRUT PIN JMPNS1.
T										
			The And 318 was							724
+			John Wood							JAJ DARP3689660
1										
					1					
			MARKAN			-				and well as an have a supply well and the supply the su
1			N2525Y TACH: 6480.8 DATE: 6 OCT. 2015							N2525Y TACH: 6548.3 DATE: 31 DEC. 2015
+			REPLACED TOP COWLING (LEFT/REAR) LATCH PIN P/N MS20392-1C21.							REPLACED STARTER PIN 149-NL (S/N FN-341589).
+										
			Charles							Blin A= P36 89860
			Attree ARP 3689868							Journal of the second
T	1.	SUB TOT				200				
		SUB-TOT					L		SUB-TOT	
40			Therefore and the second secon				1			- the control of the

No		N2525Y TACH: 6570.8 TTAF: 18,024.9 DATE: 20 JAN. 2016							
ATE	TIME RECC IN ME SERVICE TI	ADING LUBED & INSPECTED FLIGHT CONTROL HINGES PULLYS, FLAP MECH, & ELEVATOR TRIM JACKSCREW ASSY, REPLACED INDUCTION FILTER BA-16, AND VACUUM FILTER PAR RA-83-5-1.	WORK		DATE	TOTAL TIME IN SERVICE	TACH OR DECORDING	SY TACH: 6685.6 DATE: 9 JULY 2016 EPLACED ALTERNATOR PM 4111840 (SM 7616), ABIN DOOR (OUTSIDE) LOWER HANDLE ASSEMBLY	Page No
	тот	AL brd i CERTIFY THAT THIS <u>AIRCRAFT</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A 00 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.		100)			TOTAL bre	ASP 3826313	·
		A3P 382633	* 'm					77.27 33.20	
-		N2525Y TACH: 6573.3 DATE: 25 JAN. 2016		The state of the s			N2525	7 TACH: 6727.3 DATE: 29 AUG. 2016	
		REPLACED INDUCTION AIR FILTER BRACKET DUCT TUBE PIN SCAT12.			_ <	}	1 LL	LACED VACUUM PUMP P/N 211CC (S/N 166672).	K
		The HED3688802					77	A 3.P 3826313	
							Sort	i Aviation El Cajon, CA	
		N2525Y TACH: 6591.7 DATE: 8 FEB. 2016	Y						
		REPLACED MASTER CONTACTOR PIN 6041H105:					AMERICA	AVIATION ACADEMY MAINTENANCE 2035 N. Marshäll Ave.	
		A.P 88243/3	.)	10			29 St. PT 2016 Tack; 6735,3 To This are rat N2525 Y Manufac	urer: PIPER Model: PA28-161 SER: 28-8516075 Manufacture I	Date:
=							1985 was inspected using Far 4: Expiration: 07/31/2018. Service surfaces and checked tensions a	App. D. as a guide. Aircraft Registry. Certificate Issued: 10/13/ i Aircraft Battery. Serviced and Lubricated Airframe Lubed all co d travels. Inspected Tires for wear and cuts, installed brake disk	2009. ontrol
		N2525Y TACH: 6669.4 TTAF: 18,123.5 DATE: 18 MAY 2016 CHARGED BATTERY, CLEANED FUEL STRAINER SCREEN & BOWL.					inspected brakes for improper a security. Dressed blade \$1.413.43 Appendix F) 1.413.43 Appendix F) 1.413.43 Appendix F)	D. Anto trace timings P/N RAUGO-30026. Serviced brake reservoir institutes to the property of	207)
		LUBED & INSPECTED FLIGHT CONTROL. HINGES, PULLYS, FLAP MECH. & ELEVATOR TRIM JACKSCREW ASSY. REPLACED INDUCTION FILTER BA-16, VACUUM FLITER PIN RA-83-51, AND LEFT WING TIE-DOWN RING PIN 18457-000. REPLACED & PAINTED (WHITEWING WALL) RIGHT/REAR					The billion of the table of the	ned title bits onto.	ì
		I CERTIFY THAT THIS ARCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.					CONDITION. Sto.	CRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH HAS BEEN DETURMINED TO BE IN AN AIRWORTHY EXPLOYED 8 0 2 (1) ASP 30 20 23 6 F A	IAN
		A \$ P 3826813					STENEN ES	SOCIM THE STATE TO BE	
		N2525Y TACH: 6674.5 DATE: 31 MAY 2016							
		REPLACED RUDDER ASSEMBLY (WITH A SERVICEABLE UNIT) PIN 65342-02.							
	OUE -	A=P 3826313		0					
	SUB-TOTAL-	Safty-rorwand nd nextryage-				S	JB-TOTAL this page		

DATE	TOTAL TIME IN SERVICE							i WORK			
		j ,	AMERI	CAN A	VIATION	MAINT	ENANCE				
			W 53	Hiero							
			7810		4	1					
		1			MAINTENAN			1			
					Marshall Ave. El Cajon, CA 9		1				
		22 IIIN 201	Tools 716	5.3 4	Time: 8321.8	2020					
		This Aircraft	N2525Y N	fanufactur	er: PIPER Mode	l: PA-28-161	SER: 28-8516075 Manufacture Date:				
		Battery, Serv	iced and Lu	brigated A	issued: 10/13/20	U. Expiration	07/31/2018 Serviced G-35 Aircraft	1			
		mspecied 11	res for wear	and cuts	inspected brake d	ick on main to	saala inamaatad kaalaa				
		replaced of	linings for improper adjustments, Serviced brake reservoir. Replaced R/H Gas Cap P/N 6687-000. Replaced Strut Bump Stop P/N CA79072-000. Replaced Sun visors P/N RFF-300-2. Repaired landing light wire. Replaced Air Filter P/N BA16. ATC Transponder and Altimeter Test Next Due @ 7/17 As per GAP 0.14.3.3.								
		per (FAR 91	.413.43 Apr	endix F) F	ELT checked for	ansponder and	Altimeter Test Next Due @ 7/17 As				
-		10/17 AD-76	i-7-12 by Or	npiy with terations c	requirements. Ne	xt duc@ 09/17	. Replaced ELT battery next due @				
		2013-2-13 0)	rionzontai	Stabilizer	ivext due @ Tac	n: 59837.5 All	A.D.'s Checked thru this date.				
		I CERTIFY	THAT TH	IS AIRFE	RAME HAS BEE	EN INSPECT	ED IN ACCORDANCE WITH A 100				
-		CONDITIO	ection a	AND HAS	BEEN DETUR	MINED TO I	BE IN AN AIRWORTHY				
		STEVENC	ESOUILIN	A & P200	0236IA			1			
	-										
Artho	ety Country:	AUTHOR				3. Form Trucking Numb					
	nited Status on Name and Address:	FAS For	m 8136-3, Altern	EASE C	ERTIFICATE	5385930	· 1	1			
.		Textron A	Textron Aviation Inc. (Textron Aviation Inc. 1 Cessna Blvd, Wichita, K		5. Work Order Contract Tree Number:		ENANCE				
120	7, Description:	1 Cessna Bly	d, Wichita, I	KS 67215		2501327	THE REAL PROPERTY.				
12. Remarks:	SWITCH P	RESS TO	S2870-1	1	N/A	II. Sensor					
The Military	/	AUTH	ORIZED REL	EASE DO	CUMENT		r 101				
	J			#: 66707			1	1			
	ALCO DE ARRAPORTO COM TO	ne were must factured in the on the condition for safe open		in Dillinx	Olianoi Sessi 🗆 Olia	represent a product of the					
Dh Authorize	Percent design data so	ecified in 20sek 12.				The state of the s	i: PA-28-161 SER: 28-8516075 te Issued: 10/13/1909. Expiration				
19tus	Ulmba		I.A. Approvated	C4	of the board of Persons	NA ADMINISTRATION	1.				
DAM .	ped or Printed): EHMKE		I Je. Dave edistropy	m yaayir	of State Printing State of	1					
			02/Da	c/2016		- her (ell-mine);;;					
Where the users in Dlock 1, it may	s understand that the evidence performs where the essential that the user's d in Dlock I.	intence of day decreases also in accordance with the natio	Orders not intermed to	Maria Maria	ity to install the aircraft engine/peo by different thou the aircraftsmens neis! propeller(s)*ericle(s) from (f	opeller lantele.					
	d in Diock I. ocks I la and I da do no the national translation		fication, in all cases, all the aircraft may be fire			availability of the country ages he sinwerthings authority of	ifind the				
FAA Form #130	1 (02-14)	The second second	are arrests may be figure	va.	A CONTRACTOR OF THE STATE OF	NSN: 0052-00-012.	ant				
-		-	-								
			h								
_											
						•					

DATE	TOTAL TIME IN	TACH OR RECORDING METER	DESCRIPTION OF WORK PERFORMED—	Page No
	SERVICE	TOTAL	SIGNATURE & CERTIFICATE NO. OF PERSON PERFOR	MING WORK
		I OIAL brou	ght forward from previous page	
_			•	
		1	AMERICAN AVIATION MAINTENANCE	
		-		
			MAINTENANCE 1987 N. Marshall Ave. Hangar 101	
			El Cajon, CA 92020	-
			13 MAR 2017 Tach: 7064.4 Hobbs:8222.4 This Aircraft N2525Y Manufacturer: PIPER Model: PA-28-161 SER: 28- Manufacture Date: 1985 Aircraft Pariation 1985.	PE1CORE
			7/31/2018. Installed Tach from Instrument Overhaul Work Order Number	
			Operations check was satisfactory.	00301
			STEVEN C ESQUILDI A&P30202361A	
-				!
-				
_		A	MERICAN AVIATION MAINTENANCE	
			MAINTENANCE 1987 N. Marshall Ave. Hangar 101	
			El Cajon, CA 92020	
	L	This Aircra	17 Tach: 7077.2 Hobbs:8241.2 ft N2525Y Manufacturer: PIPER Model: PA-28-161 SER: 28-8516075	
		7/31/2018.	re Date: 1985 Air.raft Registry. Certificate Issued: 10/13/1909. Expiration: Installed Strut seal kit P/N JMPMS1 on R/H Main strut. check was satisfactory.	
		St	S. E. L.	
7		STEVEN (C ESQUITAN A&P3020236IA	
-				
		400		
		VAND	ERICAN AVIATION MAINTENANCE	
_			MAINTENANCE	
-			1987 N. Marshall Ave. Hangar 104 El Cajon, CA 92020	
-		15 MAY 2017 This Aircroft	7 Tash: 7093.0 Hobbs:8262.7 N2525¥ Manufacturer: PIPER Model: PA-28-161 SER: 28-8516075	
		Manufacture 1 7/31/2018, los	Date: 1985 Aircraft Registry Certificate Issued: 10/13/1909, Expiration:	*
-		wires. Remove	ed Birds nest, Uperations check was satisfactory.	
			SQUIL DV AS P30202361A	

age No		_						
DATE	TOTAL TIME IN	TACH	I COULTY that the Allomatic Precents Altitude Demonstra to	7			∋ No	
	SERVICE	MET				DATE	AMERICAN AVIATION MAINTENANCE	
		TOTA	have been performed and found to comply with FAR PART 43, Appendix E, Paragraph ©. N# 2525		100		Manufacturer; PIPER	
			Work Order to	20.	. 9		MAINTENANCE Tach: 7480.6 SER: 28-8516075 1987 N. Marshaft Ave. Hangar 101 Hobbs Time: 2728 3	
		-	Date, 8 - 20 Signature 2/ 4/13/				Work Order: 1836 El Cajon, CA 92020	
			Instrument Overhaul Service of San Diego, Inc. 1981 N. Marshall Ave, El Cajon, CA 92020				This Airframe N2525Y Was Inspected I.A.W. Manufacturers Maintenance Manual. Replaced Air Filter P#: BA16, Replaced Instrument Air Filter P# BAD0.18.1 Elbow Mac Victor Day 10 ANN March 18 (1997)	
			Phone: (619)-449-5565 FAA Cert # CB3R417L	١.			Instrument Air Filter P# RAD9-18-1 Libow Hose Vasualisenance Manual. Replaced Air Filter P# RA16, Replaced Instrument Air Filter P# RAD9-18-1 Libow Hose Vasualir Pump P# AN84-60. A Detailed List of Work is 400 W (Of #836, AD 16-7-12 by Operations Clock of Bendix Ignition Switch. Next due @ Tach: 7580,6 P/C/W AD-2013-2-13 by Horizontal Stabilizer Not to Exceed 2,000 Hours Time-in-Service or 7 years Not to Exceed 2,000 Hours Time-in-Service or 7 years Not to Exceed 2,000 Hours Time-in-Service or 7 years Not to Exceed 2,000 Hours Time-in-Service or 7 years Not due @ Tach: 1918.8	
		1		1			All A.D.'s Checked thru this date.	
			AMERICAN AVIATION MAINTENANCE				I CERTIFY THAT THIS ARPHAINT HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION THIS ARREAME OR COMMONENT HAS BEEN REPAIRED BY DOIN INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE RULES OF 14 CPE IT IS DOIN INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT WITH CURRENT AND AND IS APPROVED THE OF THE OWNER PERSONNERS. TO BE IT AN ARROWNED IT UNDITION AND IS APPROVED ITS APPROVED THE OWNER PERSONNERS.	
			THE REAL PROPERTY AND ADDRESS OF THE PERSON				MAINTENANCE RULES OF 14 CFR IT IS FOUND TO BE IN AN AIRWORTHY CUNDITION OF IS APPROVED RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.	
		Manufactu Model: PA	rer: PIPER -28-161	1			Date: 29 JAN 2019 Signed:	
		SER: 28-88 Work Orde	516075 1987 N Monthell Av. 11 Tach: 7373.4	-			For: American Aviation Maintenance Inc. CRS # 48VR16OD	
		This Airca Manufacta	raft N2525Y Had Front Tire & Tube Replaced 5.00 x 5. Replaced Brake Linings. I.A. W. urer M.M. A List of Detailed Work is Under W/O# 1733. Ground Check Satisfactory.				·	
		CONDITION	THAT THIS AIRFRAME OR COMPONENT HAS BEEN REPAIRED AND /OR INSPECTED AS OUTLINED ACCORDANCE WITH CURRENT MAINTENANCE RULES OF 14 CFR IT IS FOUND TO BE IN AN AIRWORTHY NAND IS APPROVED RETURN TO SERVICE WITH RESPECT TO THE WORK CERFORMED.	1				
			Date of Hillians				American aviation maintenance	
			For: American Aviation Maintenance Inc. CRS # 48VR16OD				Manufacturer: PIPER 13 JUNE 2019	
	F-1	rms. in a			_		Model: PA-28-161 MAINTENANCE Tach: 7580,0 SER: 28-8516075 1987 N. Marshall Ave, Hangar 191	
							Work Order: 1928 El Cajon, CA 92020	
			AMERICAN AVIATION MAINTENANCE		/		This Airframe N2525Y Was Inspected I.A.W. Manufacturers Maintenance Manual. Replaced Air Filter P#: BA16, Replaced Brake	
	Mode	ufacturer: P. el: PA-28-1	61 MAINTENANCE . 02 OCT 2018	-			Linings P# RA066-30026, Flap Return Springs P# 62820-06, Flap Spring P# 62821-00. A Detailed List of Work is Under W/O# 1928, AD-76-7-12 by Operations Check of Bendix Ignition Switch, Next due @ Tach: 7680.0 P/C/W AD-2013-2-13 by Horizontal	
	Work	28-851607 Order: 175					Stabilizer Not to Exceed 2,000 Hours' Time-in-Service or 7 years Next due @ Tach: 9181.8 All A.D.'s Checked thru this date.	
	This	Airframe N	789EV C				I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION THIS AIRFRAME OR COMPONENT HAS BEEN REPAIRED AND / OR INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE ROLLES OF 14 CPR IT IS FOUND TO BE IN AN AIRWORTHY CONDITION, JAMP IS APPROVED RETURN TO SERVICE	
1			2525 Y Serviced G-35 Aircraft Battery, Serviced and Lubricated Airfinme Lubed, All Control Surfaces and Checked Linings for Inproper Adjustments, Serviced Brake Disc on Main Wheels, LPE: 0.215 R/H: 0.214 Inspected Linings for Improper Adjustments, Serviced Brake Reservoir with \$566 Renthered A.		-		MAINTENANCE RULES OF 14 CFR IT IS FOUND TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED RETURN TO SERVICE WITH RESPECT TO THE WORK PERPORMED.	
	Wind: Next I	shield P# W	Limings for Ingroved lites for Wear and Cuts, Inspected Brake Disc on Main Wheels, 1.Hz; 0.215 RNI; 0.214 Inspected Limings for Ingroper Adjustments, Serviced Brake Reservoir with \$566. Replaced Air Filter Pi: BA16. Replaced G2039-11-2501.H & RVH. A Detailed List of Work is Under W/O# 1788, ATC Improputed and Air filter Pi: BA16. Replaced A8 per GRAP 91.43.43 Appendix P JELT Clecked for Signs) **				Date: 13 JUNE 2019 Signed:	
- 1	Opera	tions Check	d to Comply with Requirements. Next Duc@ 10/19. Replacet ELT Battery Next Duc@ T1/19-XX 10/2-XX				For American Aviation Maintenance Inc. CRS # 48VR16OD	
	4,000	FROUTS 11000	2-in-Service or 7 years Next due @ Tach: 7481.0 P/C/W AD-2013-2-13 by Horizzontal Stabilizer Not to Exceed ed thru this date.				/	
	I CERT	TIFY THAT	THIS AIRPRAME HAS BEEN INSPECTED IN ACCORDANCE WITH THE SAME SAME AND ACCORDANCE WITH THE SAME SAME SAME SAME SAME SAME SAME SAM		1			
	MAIN' WITH	TENANCE R RESPECT T	THIS AIRPRAME HAS BEEN INSPECTED IN ACCORDANCE WITH S BEEN REPAIRED AND O'R INSPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT UILES OF I CFE IT IS FOUND TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED RETURN TO SERVICE O'THE WORK PERFORMED.	1	-		AMERICAN AVIATION MAINTENANCE	
	-		///				Manufacturer: PIPER 17 JULY 2019	
	4	Date:	92 OCT 2018 Signed: American Aviation Maintenance Inc. CRS # 48VR16OD				Model: PA-28-161 MAINTENANCE Tach: 7680.1	
81	1			1				
					+		This Airframe N2525Y Was Inspected LA.W. Manufacturers Maintenance Manual. Replaced Air Filter P#BA16, Replaced Serviceable L/H Landing Gear Piston P# 65319-04. Replaced L/H Main Strut Seal Kit P# P8S-KT-10, Replaced R/H Side Fuel Tank	
			ATTAF:18,835.1				Drain Valve P# CCA36150, A Detailed List of Work is Under W/O# 1956. AD-76-7-12 by Operations Check of Bendix Ignition Switch, Next due @ Tach: 7780.7 P/C/W AD-2013-2-13 by Horizontal Stabilizer Nat to Exceed 2 000 Hours' Time in Section at 7	
							years Noxt due @ Tach: 9181.8 All A.D.'s Checked thru this date.	
							I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION THIS AIRFRAME OR COMMUNENT HAS BEEN REPAIRED AND /OR RISPECTED AS OUTLINED ABOVE IN ACCORDANCE WITH CURRENT MARTENANCE RULES OF 14 CERT ITS FOUND TO BE IN AIR AIRWORTHY COMPITION AND A PEPROVED BETURN TO SERVICE	
				0	A		MARYENANCE RULES OF 14 CFR IT IS FOUND TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED RETURN TO SERVICE WITH RESPECT TO THE WORK PERFORMED.	
		CHD T	TAL 41		57			(32)
-			DTAL this page				Date: 17 JULY 2019 Signed: For: American Aviation Maintenance Inc. CRS # 48VR16OD	
		TOTAL-	Carry forward to next page					
						L	Page All Andrews	

Page No			N2525Y TACH: 7779.5 TTAF: 17779.5 DATE: 18 NOV. 2019			1			,	
DATE	TOTAL TIME IN SERVICE	The aircraft	CHARGED BATTERY, CLEANED PUEL STRAINER SCREEN & BOWL LUBED & INSPECTED FLIGHT CONTROL HINGES, PULLYS, FLAP MECH. & ELEVATOR TRIMMCKSCREW ASSY. REPLACED INDUCTION FLIER BA-15. VACUUM FILTER PIN RA-B3-5-1, INSTRUMENT FILTER PIN RA-D9-18-1, BRAKE- MASTER CYLINDER (2) BRACKETS PIN B3468-00, BRAKE MASTER CYLINDER (2) BRACES PIN B346-00, AND MAP LIGHT PIN 1816. REMOVED, REPACKED (GREASE), AND REINSTALLED ALL (6) WHEEL BEARINGS. I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL, INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. SORTIA AVIATION SORTIA AVIATION TIT 19,228.5 Tach	7796.4 Per 28-161	On the		11	Replaced 7 7 7 8 7 8 7 8 7 7 8 7 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 8	MAINTENANCE 1987 N. Marshall Ave. Hangar 101 El Cajon, CA 92020 frame N2525Y Was Inspected I.A. W. Manufacturers Maintenano hir Filter P#:BA16, Brake Disc P#164-02000, Lower Flap Spring Nose Steering Springs P# 487-483, Oil Cooler Spacer P#86062-09 viced L/H Main Strut. A Detailed List of Work is Under WiCh? 2-712 by Operations Check of Bendix Ignition Switch, Next due & ontal Stabilizer Not to Exceed 2,000 Hours' Time-in-Service or 7 All A.D.'s Checked Through This Date. EEN INSPECTED IN ACCORDANCE WITH A 109 HOUR INSPECTION THE TLINKD ABOVE IN ACCORDANCE WITH CURRENT MAINTENANCE BUT TION AND IS APPROVED RETURN TO SERVICE WITH RESPECT 10 HE steenance Inc. CRS # 48VR16OD	: P#487-269, 94, :1880. @ Tach: 7978.8 7 years Next duc @ Tach: 9181.8
		Manufacturer: I Model: O-320-I SER: L-8213-35	MAINTENANCE	24 JAN 2020 Tach: 7796.4				1.0. Shortest Aviation Mail	tenance inc. CRS # 45VR16UD	=
		Dampers & St I CERTIFY THA: RULES OF 14 CF TO THE WORK I	BI Cajon, CA 92020 BI Cajon, CA 92020 BI Cajon, CA 92020 RESEARCH STATES AND CASES	alled Shimmy story.	<i>∞</i> 2	0				
	Ţ	Manufacturer: Ly Model: 0-320-D3	AMERICAN AVIATION MAINTENANCE	27 JAN 2020						- 1
		I CEPTER THAN		Tach: 7799,7 rbs Time: 9191.7 7. Operational						
	-	Date:	27 JAN 2020 Signed: Signed Aviation Maintenance Inc. CRS # 48VR160D	THE RESPECT						
		SUB-TOTAL			0			SUB-TOT	AL this page	
1	- 5	TOTAL -Care	I forward to novt page		-	1.				