

1. Approving Civil Aviation Authority/Country: FAA/United States		<b>2. AUTHORIZED RELEASE CERTIFICATE</b> FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number: 2240-1	
4. Organization Name and Address: R & C Aviation Inc. 293 Polk 52, Mena AR 71953 CRS# R38R898Y					5. Work order/Contract/Invoice number: W/O 2240 W/C 1	
6. Item:	7. Description	8. Part Number	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	L/H Heated Windshield	45213	1	4-H-7-8-05	Repaired	
12. Remarks: Performed detailed visual inspection IAW Piper Cheyenne Service Manual 6H2. Checked heater leads for continuity. No unacceptable defects noted at this time.						
13a. Certifies the items identified above were manufactured in conformity to:  <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-Approved design data specified in Block 12			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other Regulation Specific to Block 12  Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval Authorization No.:	14b. Authorized Signature: 		14c. Approval/Certificate No.: R38R898Y	
13d. Name (Typed or Printed):		13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): Chris Cox		14e. Date (dd/mmm/yyyy): 07 / FEB / 2025	
<b>User/Installer Responsibilities</b>						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.						
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engines(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.						
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

<b>R &amp; C AVIATION, INC. CRS #R38R898Y</b>				CODE:	ESTIMATE:	W/O 2240
AIRCRAFT:	MAKE:	MODEL:	REGISTRATION #:	S/N #: 4-H-7-8-05	W/C #: 1	
TOTAL:	TIME:	CYCLES:	P/N 45213	CUSTOMER AUTHORIZATION:		

DISCREPENCY:  
L/H Heated Windshield

ORIGINATED BY: Christopher Cox	DATE: 02/06/2025
-----------------------------------	---------------------

CORRECTIVE ACTION:  
Performed detailed visual inspection IAW Piper Cheyenne Service Manual 6H2. Checked heater leads for continuity. No unacceptable defects noted at this time.

CORRECTED BY: *[Signature]* EMP # *121* DATE: *2-7-24* INSPECTED BY: *cox 198* DATE: *2-7-24*

OPS. CK     LK. CK.    Mechanic    INSPECTOR

RII REQ.     YES     NO    STAMP: